

# Final Classifications



## 2006 Subaru Safari Tasmania

Retirements



Listed By Vehicle No

Veh	Heat	Reason
5	1	SS2 Engine
9	1	SS2 Hole in Fuel Tank
19	1	Service A Out of late time
20	1	SS6 Rolled
21	2	SS16 Mechanical
26	2	SS19 Broken Front Driveshaft