



## 2006 NGK Rally of Melbourne

Retirements



Listed By Vehicle No

Veh	Heat	Reason
17	2	SS9 off road
19	1	After SS7 Turbo
20	1	SS7 Rolled
20	2	Did not start heat 2
21	1	After SS7 Oil leak
22	2	Did not start heat 2
29	1	SS8 Off road
31	2	Service B withdrawn