



2006 RaceTECH Steel Victorian Rally Championship

Retirements



Listed By Vehicle No

Veh	Heat	Reason
20	1	SS7 Rolled
20	2	Did not start heat 2
21	1	After SS7 Oil leak
29	1	SS8 Off road
44	1	SS6 Hit tree
44	2	Did not start heat 2
45	1	After SS4 Blown Turbo
48	2	SS9 Hit tree
56	1	Service B Ball joint broke
57	1	SS2 Faulty Ignition
57	2	Did not start heat 2
60	1	SS2 Gearbox
61	1	Service B Head gasket