



2006 Subaru Capital Rally

Retirements

Listed By Vehicle No



Veh	Leg	Reason
104	2	SS11 Front suspension
105	2	After SS9 Clutch
106	1	SS7 DNF Broken drive train
106	2	SS9 Broken drivetrain
109	2	SS10 Mechanical
110	2	SS10 Mechanical
111	1	SS7 DNF Rolled
113	2	SS12 Broken driveshaft
115	1	SS1 Off Road
116	1	After SS1 Drive shaft
119	2	After SS13 DNF
122	1	SS4 DNF Broken Crankshaft
123	2	SS12 No power
124	1	SS4 Ball joint
125	1	After SS2 Drive train problem
125	2	SS9 Mechanical
127	1	SS1 Stuck on run-off
127	2	SS10 Mechanical
128	2	SS12 DNF